

Webasto Thermo Top EVO5 H87 Permanent Lockout Reset Procedure

Reset Procedure

Permanent lock out (H87) reset procedure for Thermo Top EVO5

Note: When using the digital multi-control and the H87 error displays, press the control knob to acknowledge the error

- 1 Turn off the heater using either controller or switch
- 2 Remove 20A Fuse
- 3 Wait 30 seconds and then refit 20A Fuse
- 4 Wait 30 seconds
- 5 Turn Heater on using controller/switch & then remove 20A fuse between 3 and 10 Seconds
- 6 Wait 30 seconds and then refit 20A Fuse
- 7 Turn off the heater using controller/switch
- 8 Wait 30 seconds
- 9 Turn Heater on - procedure complete



H87 error displayed on
multi-control only